



默认焊接R1、R3，R2、R5默认不焊接

FB1、FB2焊接时采用总线电源供电

<https://mfweb.top/>

Title		
USB HUB By Mfweb Bi Fang Electronic Technology CO.,LTD		
Size	Number	Revision
A3		
Date:	2017/4/10	Sheet of
File:	G:\单片机项目\mainSCH.Doc	Drawn By: